



# **Intel® Open Source HD Graphics and Intel Iris™ Plus Graphics**

## **Programmer's Reference Manual**

For the 2016 - 2017 Intel Core™ Processors, Celeron™ Processors,  
and Pentium™ Processors based on the "Kaby Lake" Platform

Volume 16: Workarounds

January 2017, Revision 1.0



## Creative Commons License

**You are free to Share** - to copy, distribute, display, and perform the work under the following conditions:

- **Attribution.** You must attribute the work in the manner specified by the author or licensor (but not in any way that suggests that they endorse you or your use of the work).
- **No Derivative Works.** You may not alter, transform, or build upon this work.

## Notices and Disclaimers

INFORMATION IN THIS DOCUMENT IS PROVIDED IN CONNECTION WITH INTEL® PRODUCTS. NO LICENSE, EXPRESS OR IMPLIED, BY ESTOPPEL OR OTHERWISE, TO ANY INTELLECTUAL PROPERTY RIGHTS IS GRANTED BY THIS DOCUMENT. EXCEPT AS PROVIDED IN INTEL'S TERMS AND CONDITIONS OF SALE FOR SUCH PRODUCTS, INTEL ASSUMES NO LIABILITY WHATSOEVER AND INTEL DISCLAIMS ANY EXPRESS OR IMPLIED WARRANTY, RELATING TO SALE AND/OR USE OF INTEL PRODUCTS INCLUDING LIABILITY OR WARRANTIES RELATING TO FITNESS FOR A PARTICULAR PURPOSE, MERCHANTABILITY, OR INFRINGEMENT OF ANY PATENT, COPYRIGHT OR OTHER INTELLECTUAL PROPERTY RIGHT.

A "Mission Critical Application" is any application in which failure of the Intel Product could result, directly or indirectly, in personal injury or death. SHOULD YOU PURCHASE OR USE INTEL'S PRODUCTS FOR ANY SUCH MISSION CRITICAL APPLICATION, YOU SHALL INDEMNIFY AND HOLD INTEL AND ITS SUBSIDIARIES, SUBCONTRACTORS AND AFFILIATES, AND THE DIRECTORS, OFFICERS, AND EMPLOYEES OF EACH, HARMLESS AGAINST ALL CLAIMS COSTS, DAMAGES, AND EXPENSES AND REASONABLE ATTORNEYS' FEES ARISING OUT OF, DIRECTLY OR INDIRECTLY, ANY CLAIM OF PRODUCT LIABILITY, PERSONAL INJURY, OR DEATH ARISING IN ANY WAY OUT OF SUCH MISSION CRITICAL APPLICATION, WHETHER OR NOT INTEL OR ITS SUBCONTRACTOR WAS NEGLIGENT IN THE DESIGN, MANUFACTURE, OR WARNING OF THE INTEL PRODUCT OR ANY OF ITS PARTS.

Intel may make changes to specifications and product descriptions at any time, without notice. Designers must not rely on the absence or characteristics of any features or instructions marked "reserved" or "undefined". Intel reserves these for future definition and shall have no responsibility whatsoever for conflicts or incompatibilities arising from future changes to them. The information here is subject to change without notice. Do not finalize a design with this information.

The products described in this document may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

Implementations of the I2C bus/protocol may require licenses from various entities, including Philips Electronics N.V. and North American Philips Corporation.

Intel and the Intel logo are trademarks of Intel Corporation in the U.S. and other countries.

\* Other names and brands may be claimed as the property of others.

**Copyright © 2017, Intel Corporation. All rights reserved.**



## Table of Contents

<b>Workarounds</b> .....	<b>1</b>
<b>Display Workarounds</b> .....	<b>19</b>





## Workarounds

This page lists all BSpec narrative workarounds for Gen9 (SKL/BXT/GLK/GLV). Note that the functional area for each item is listed below, so you can search on this value or other content on this page. Also note that a "BSpec ID" has been assigned to make it easier to reference these items.

BSpec ID	Functional Area/Component	Workaround Name	Workaround Description	Valid Steppings
0538	KMD	WaSkipStolenMemoryFirstPage	WA to skip the first page of stolen memory due to sporadic HW write on *CS Idle	KBL: SIWA_UNTIL_B0
0550	KMD	WaForceEnableNonCoherent	Must Force Non-Coherent whenever executing a 3D context. This is a workaround for a possible hang in the unlikely event a TLB invalidation occurs during a PSD flush. Set masked bit 4 in 0x7300 during boot.	KBL: UNTIL_D0
0551	KMD	WaDisableMidThreadPreempt	Disable GPGPU thread-level (a.k.a. mid-thread) preemption on parts (until B0) since validation was minimal on those parts.	KBL: SIWA_FOREVER
0556	KMD	Wa4x4STCOptimizationDisable	HIZ/STC hang in hawx frames. W/A: Disable 4x4 RCPFE-STC optimization and therefore only send one valid 4x4 to STC on 4x4 interface. This will require setting bit 6 of reg. 0x7004. Must be done at boot and all save/restore paths.	SIWA_FOREVER
0566	KMD	WaModifyVFESateAfterGPGPUpreemption	GPGPU preemption hang or corruption issue. This WA must be applied before re-submitting a GPGPU preempted workload. SW needs to do two things.	KBL: SIWA_UNTIL_D0



## Workarounds

BSpec ID	Functional Area/Component	Workaround Name	Workaround Description	Valid Steppings
			<ol style="list-style-type: none"><li>SW should detect if VFE unit in the context image have LRI commands to 0x54AC and 0x54B0. SW does that by checking if the LRI header at context image offste (0x0E90) &lt;in VFE&gt; is 0x11001003 and the two MMIO offsets in this LRI is 0x54AC and 0x54B0. If so, do this- D0 (LRI header): 0x1100_1003 -&gt; 0x1100_1001 D1 (1st MMIO offset): 0x0000_54AC -&gt; Leave this dword untouched D2 (1st MMIO offset value): 54AC_DATA -&gt; Leave this dword untouched D3 (2nd MMIO offset): 0x0000_54B0 -&gt; Overwrite to 0x0 D4 (2nd MMIO offset value): 54B0_DATA -&gt; Overwrite to 0x0</li><li>Apart from it SW must also increment the Batch Buffer Address by Walker Command Length so that CS moves to the command following it. Size of Walker should be 0xF *</li></ol>	

Workarounds



BSpec ID	Functional Area/Component		Workaround Name	Workaround Description	Valid Steppings
				sizeof(DWORD) = 0x3C Bytes	
0572	KMD	RTL	WaFlushCoherentL3CacheLinesAtContextSwitch	Coherent L3 cache lines are not getting flushed during context switch which is causing issues like corruption. Need to set bit 21 of MMIO b118, then send PC with DC flush and then reset bit 21 of b118. This programming sequence needs to be part of the indirect context WA BB	SIWA_FOREVER
0574	KMD		WaDisableSDEUnitClockGating	WA for GPGPU workload hang for which requirement is to disable SDE Unit clock gating. This is done by setting bit 14 of MMIO 9430.	KBL: SIWA_UNTIL_B0
0581	KMD		WaSetVfGuardbandPreemptionVertexCount	Workaround for potential 3d preemption bug that can cause data corruption. Driver should write to register 0x83A4 (preemption vertex count) and set a value of 0x20. At boot, write 0xffff0020 to 0x83a4 (it's a masked register).	KBL: SIWA_UNTIL_B0
0590	KMD		WaSkipInvalidSubmitsFromOS	For Invalid submits from OS - simply report fence completion without submitting the DMA buffer to GPU.	SIWA_FOREVER
0592	3D		SKL_Z_16X_ALIGNMENT	TileY cannot be used for MSAA 8x or 16x with multiple MIP levels. The fallback is to use TileYF. Tile YS would also be suitable.	
0673	3D		WaStallBeforePostSyncOpOnGPGPU	Preemption mid-thread focused test failures.	SIWA_FOREVER



## Workarounds

BSpec ID	Functional Area/Component	Workaround Name	Workaround Description	Valid Steppings
			<p>WA:</p> <p>PIPECONTROL command with "Command Streamer Stall Enable" must be programmed prior to programming MI_SEMAPHORE_SIGNAL command with Post-Sync Operation set in GPGPU mode of operation (i.e when PIPELINE_SELECT command is set to GPGPU mode of operation).</p> <p>PIPECONTROL command with "Command Streamer Stall Enable" must be programmed prior to programming MI_ATOMIC command with Post-Sync Operation set in GPGPU mode of operation (i.e when PIPELINE_SELECT command is set to GPGPU mode of operation).</p> <p>PIPECONTROL command with "Command Streamer Stall Enable" must be programmed prior to programming a PIPECONTROL command with Post Sync Op in GPGPU mode of operation (i.e when PIPELINE_SELECT command is set to GPGPU mode of operation).</p>	



Workarounds



BSpec ID	Functional Area/Component	Workaround Name	Workaround Description	Valid Steppings
0675	3D	WaFlushBefore3DSTATEGS	GS_SIMD8_OTHANDLE_RELAX test hanging due to an issue in gs_trg clock gating logic. WA: Add state_osb_statedv into trg_cg equation.	SIWA_FOREVER
0677	3D	WaDisableLosslessCompressionForSampleL	Sampler Throughput drop with lossless enabled for 0% & 50%, compression tests with 100%bypass. WA: Disabe double-fetch.	SIWA_FOREVER
0680	3D	WaDisableSamplerL2BypassForTextureCompressedFormats	RTL DM producing Xs for SC output. WA: Disable Bypass on some of the compressed formats.	SIWA_FOREVER
0681	3D	WaCompressedResourceSamplerPbeMediaNewHashMode	BXT GFXDRV: Hot spotting issue with render target compression. WA: Align lossless compressed resource allocations to 2MB or have fixed virtual addresses. This WA is specifically for steppings where HW will not fix.	KBL:SIWA_FOREVER
0683	3D	WaCompressedResourceDisplayNewHashMode	BXT GFXDRV: Hot spotting issue with render target compression. WA: Align lossless compressed resource allocations to 2MB or have fixed virtual addresses. This WA is specifically for steppings where HW will not fix.	KBL:SIWA_FOREVER



## Workarounds

BSpec ID	Functional Area/Component	Workaround Name	Workaround Description	Valid Steppings
0689	3D	WaPipeControlBeforeVFCacheInvalidationEnable	Vf randomly decodes nullprim packets as state packets causing illegal internal states in it. WA: B2B control packets to be sent when VS_cache_enable is programmed to be enabled. First control packet with bit11 as '0' and the next control packet with bit11 as '1'.	SIWA_FOREVER
0693	3D	WaEnableTiledResourceTranslationTables	Support for Sparse Tiled Resources under SVM	KBL:SIWA_FOREVER
0695	3D	WaIndependentAlphaBlend	GFX SV: optHizClear test miscompares in B0 silicon. WA: Fixed optimization case for independent alpha to look at src values for RGB and Alpha values separately. Fixed the src0dest1 case for alpha component to look at src_alpha_is_zero instead of src_is_zero.	KBL:SIWA_FOREVER
0696	3D	WaBindlessSurfaceStateModifyEnable	Missing "Size Modify Enable" Bit For Bindless Sizes in STATE_BASE_ADDRESS. WA: The suggested WA is that when NOT setting the modify enable bit for Bindless Surface State Base Address, program the dword length to "Eh" instead of "11h" and zero out the last 3 DW or not send them.	SIWA_FOREVER

Workarounds



BSpec ID	Functional Area/Component		Workaround Name	Workaround Description	Valid Steppings
0699	3D		WaAtomicFlushOnInterfaceDescriptor	GPGPU Preemption - Hang on Barrier WA: VFE need to make sure that all previous indirect prefetches are done after VFE state command. MI_ATOMIC_FLUSH need to be programmed between ID load commands or curbe load commands if it back to back.	KBL:SIWA_FOREVER
0701	3D		WaStructuredBufferAsRawBufferOverride	BSpec restricts Data Port access using Untyped Surface Read/Write to RAW surface format only. WA: Raw format support added in svsmunit.	KBL:SIWA_FOREVER
0702	3D			False Inexact IEEE flag set by SP to UQ mov. WA: Cannot use flags with float2int conversion with non-RTZ rounding mode.	
0714	Media	VTQ		Trellis quantization performance improvements introduced a bug. The bug results in Hang condition when Chroma Trellis is disabled and Trellis is enabled. The bug is fixed in KBL B0.	KBL A0
0744	3D		WaDisableRTReadsfor1DSurfaces	Failing to implement the following WA will lead to pixel corruptions due to accesses to WA : If RenderSurfaceState::Surface Type == SURFTYPE_1D, SW must ensure that Pixel Shaders do not generate RT reads.	KBL:SIWA_A0



## Workarounds

BSpec ID	Functional Area/Component		Workaround Name	Workaround Description	Valid Steppings
0752	3D		WaSamplerResponseLengthMustBeGreaterThan1	Dcs_pwc_rc signal is not set when notify clear comes out of phase WA: disable MMIO reads from GW & all sampler sends in GPGPU workloads with response length of 1.	KBL:SIWA_FROM_A0
0756	Media	HEVC		VP9 Decoder 8Kx8K SV test failing with miscompare at 2nd frame. WA: Frame size supported in BXT is 4Kx4K.	KBL:SIWA_FROM:A0
0827				Moved to Display Workaround page	
0828				Moved to Display Workaround page	
0831	KMD		WaDisableSamplerPowerBypassForSOPingPong	SI can get stuck ping ponging rows in a 2-2-2 fashion instead of 1-1-1 leading to a ~3% performance reduction.  WA: Disable sampler power bypass to avoid negatively impacting SO 'ping-pong' performance.	KBL:SIWA_FOREVER
0837	GAM		WaSpuriousIOMMUFaults	GT GAM HW prefetches context (or extended context) entry when a context is loaded, root pointer is updated or when there is a context cache flush. This prefetch happens without a memory transaction from the context. On this prefetch, if the context entry is a NULL (P=0), HW will generate a fault – invalid context entry. However, it is legal to have a NULL context entry, as long as no	KBL:ALL

Workarounds



BSpec ID	Functional Area/Component		Workaround Name	Workaround Description	Valid Steppings
				<p>memory references are done via that context entry.</p> <p>WA: To avoid these spurious DMA faults, SW should mark the context entry as present (not a NULL entry), and mark the page tables as not present.</p>	
0838	GTI			<p>MGSR hang when MsgCh cycle arrives a couple clocks after IOSF SB shadow request.</p> <p>This is being brought up into the SW WA section for completeness. 0xD00[3:1] already indicate that bits should be set by SW.</p> <p>WA: Enable 0x0D00[3:1] fixes in SW for all Gen9 products.</p>	KBL:ALL
0851				Moved to Display Workaround page	
0852				Moved to Display Workaround page	
0856				Moved to Display Workaround page	
0857				Moved to Display Workaround page	
0858	3D	Sampler		CSS AUX surfaces must not be on pages that can fault.	KBL:SIWA_UNTI L_D1
0859				Moved to Display Workaround page	
0860	GTI	GAM		When only the coherent flush FSM and HDC invalidation FSMs are active, GAM can turn off the clocks after receiving COH flush done even if HDC	KBL:A0,B0



## Workarounds

BSpec ID	Functional Area/Component		Workaround Name	Workaround Description	Valid Steppings
				FSM is active. This can cause invalidation end to not be sent to HDC after HDC FSM completes.  WA: Turn off GAM clock gating by setting  0x9400[22] to '1	
0864	GTI	GAM		When only the coherent flush FSM and HDC invalidation FSMs are active, GAM can turn off the clocks after receiving COH flush done even if HDC FSM is active. This can cause invalidation end to not be sent to HDC after HDC FSM completes.  WA: Turn off GAM clock gating by setting  0x9400[22] to '1	KBL:A0/B0
0865	GTI	GAM		The dynamic credit sharing between engines has an issue which can cause the credits to be lost. When sufficient credits are lost the BW through GAM can get severely limited and can eventually block all the transactions and hang.  WA: Turn off dynamic credit sharing by setting  0x4AB8[28] to '1	KBL:A0/B0



BSpec ID	Functional Area/Component		Workaround Name	Workaround Description	Valid Steppings
0866	GTI	GAM		<p>Issue here is with QBI and GFXIDLE -</p> <p>If QBI is in progress and we get GFXIDLE, it will be ACKED and it will make CTX inactive. Once CTX will go inactive it will make all pasid/ctxid match flags zero which is one of the condition for generating hdc_end for QBI. QBI will end but HD will not see end due to this Flag.</p> <p>WA:</p> <p>CS to send invalidation to GAM before indicating IDLE, GAM can handle future QBI's without involving HDC and this bug wont be exposed. Insert Pipecontrol with invalidation flag set at the end of the ring, batch. Same is required while pre-empting the existing WL.</p>	KBL:A0/B0
0867	GTI	GAM		<p>When HDC/EUs are set to Faul&amp;Halt mode, the commit interface between HDC and EUs are disabled. If coherency is enabled, we can have coherent cycles in the fabric when an external invalidation arrives, and can lead into the GAM coherent deadlock scenario if GAM resources are full. GAM deadlock coherent_flush will</p>	KBL:ALL



## Workarounds

BSpec ID	Functional Area/Component		Workaround Name	Workaround Description	Valid Steppings
				<p>kick in to resolve the deadlock. However, this requires EUs to re-dispatch the coherent cycles that were killed. If HDC/EU are in Fault&amp;Halt mode, this re-start is not possible from the EUs.</p> <p>Do not use Fault&amp;Halt as the fault mode in HDC/EU</p>	
0868				Moved to Display Workaround page	
0870				Moved to Display Workaround page	
0871				Moved to Display Workaround page	
0872	3D	CS		<p>Global Workaround Batch Buffer will not execute when enabled and Execution List mode is enabled.</p> <p>WA: Do not enable Global WABB when in Execution List mode.</p>	KBL:ALL (except GT4)
0873				Moved to Display Workaround page	
0875	GTI	GAM		<p>When there is a TLB invalidation with a Fence,</p> <p>GAM blocks the arbiters to drain the fabric for the Fence. Once the fabric is drained, the TLBs are invalidated, as well as a HDC TLB invalidation request is sent to the HDC. GAM expects an ack for this from HDC. If there are cycles in HDC that has already used the address translations, they need to be drained from HDC</p>	KBL:A0/B0





BSpec ID	Functional Area/Component	Workaround Name	Workaround Description	Valid Steppings
			<p>before it can send the Ack. GAM is supposed to unblock the arbiters at this stage to allow for these cycles to drain. However, when TRTT is enabled, the arbiter is GATR does not get unblocked until the HDC inval Ack is completed. This causes a deadlock where HDC cannot send the Ack as there are cycles that needs to drain.</p> <p>In general when CS issues a Fence Inval, there should not be any pending cycles in HDC if a CS stall is put in before and after the fence inval. However, in the case of lite restore, Fence Inval can happen asynchronously, potentially leaving pending cycles.</p> <p>The WAs for this issue are:</p> <ol style="list-style-type: none"> <li>1. Disable TRTT – so the fabric does not continue to get blocked in GATR after the fence</li> <li>2. Disable lite restore – so we do not have asynchronous fence inval events. Also need to have a CS stall before and after CS fence inval.</li> </ol> <p>SW is planning on having both Was available, and #1 as the default.</p>	



## Workarounds

BSpec ID	Functional Area/Component		Workaround Name	Workaround Description	Valid Steppings
0876	GTI	CS	WaForceCsStallOnTimestampQueryOrDepthCount	<p>Due to known HW issue specific to GT4; on a specific incident (few HW events must happens on the same clock under certain programming conditions) address, data and control fields corresponding to a PIPECONTROL command will get registered wrongly in hardware. Following this incident Fence Reports, Depth Statistic Report (Occlusion Query) and time_stamp reports will get corrupted leading to OS/KMD/UMD hangs.</p> <p><b>Workaround (option-1):</b></p> <p>PIEPCONTROL command programmed with "Post Sync Operation" set to "Write Timestamp" or "Write Depth Query" must also set "Command Streamer stall Enable" to '1'.</p> <p><b>Workaround (option-2):</b></p> <p>Software must memorize the event of programming "Post Sync Operation" set to "Write Timestamp" or "Write Depth Query" and must set "Pipecontrol Flush Enable" on next PIPECONTROL programmed.</p> <p>Note: Since the passing on the memorized event between UMD and</p>	KBL:GT4 (all GT4 SKU's)



BSpec ID	Functional Area/Component		Workaround Name	Workaround Description	Valid Steppings
				<p>KMD (ring buffer and batch buffer) is difficult, one way it could be addressed in following way.</p> <p>KMD must always program the first PIPECONTROL being programmed in the ringbuffer following the MI_BATCH_BUFFER_START with "Pipecontrol Flush Enable" set. KMD must always program PIPECONTROL with "Pipecontrol Flush Enable" set prior to programming MI_BATCH_BUFFER_START in the ring buffer. <b>OR</b></p> <p>UMD must always program the first PIPECONTROL in the batch buffer with "Pipecontrol Flush Enable" set and must always program the last command in every dispatch of the batch buffer to a PIPECONTROL with "Pipecontrol Flush Enable" set.</p>	
0877	3D	Pixel Shader	WaSendDummyConstantsForPS	<p>Hang possible when pixel shader dispatched with only header phases (R0-R2)</p> <p>WA: Enable a non-header phase (e.g. push constant) when dispatch would have been header-only.</p>	KBL:ALL
0880				Moved to Display Workaround page	
0881				Moved to Display Workaround page	



## Workarounds

BSpec ID	Functional Area/Component		Workaround Name	Workaround Description	Valid Steppings
0883				Moved to Display Workaround page	
0884				Moved to Display Workaround page	
0889				Moved to Display Workaround page	
0890				Moved to Display Workaround page	
0893				Moved to Display Workaround page	
0898	Media			WA: In encoder mode, create tiles either in horizontal or vertical direction but not in both directions.	KBL:ALL
0908	SFC	SFC Crop Limitation for VEBOX+SFC Mode	WaDisableSFCSrcCrop	<p>Below are the cases to switch from SFC to Render for VEBOX+SFC mode</p> <p>Case 1. ((SurfaceHeight &gt; 1120) &amp;&amp; (Top &gt; 1120))</p> <p>Case 2. ((SurfaceHeight &gt; 1120) &amp;&amp; (Bottom &lt; SurfaceHeight))</p> <p>Case 3. ((SurfaceHeight &gt; 1120) &amp;&amp; (Left &gt; 0))</p> <p>Case 4. ((SurfaceHeight &gt; 1120) &amp;&amp; (Right &lt; SurfaceWidth))</p>	KBL A0
0909	GS PrimID bug with Tessellation	Peter Doyle		GS Clock gating must be disabled under the following conditions: Tessellation enabled, GS enabled, GS PrimitivID enabled.	KBL: ALL

Workarounds



BSpec ID	Functional Area/Component		Workaround Name	Workaround Description	Valid Steppings
0910	GAM	Niran Cooray		<p>When DINVE=0 in the ext context entry PASID state table is not used. But, HW reads the PASIDSTPTR from the context entry and goes through SL translations, if NESTE is enabled. If the SL translation returns invalid, all transactions from that engine is considered invalid.</p> <p>WA: Have a valid GPA for the PASIDSTPTR which has a valid GPA-&gt;HPA mapping in the SL tables. This SL translation need to have R=W=1 permissions</p>	<p>KBL:UNTIL_GT2: A0-C0</p> <p>KBL:UNTIL_GT3: D0</p> <p>KBL:UNTIL_GT4: E0</p>
0915	HDC	Atomic Counter		<p>Hang occurs with Atomic Counter message with binary operations (i.e. have a separate data operand), in some dynamic load situations.</p> <p>WA: Replace use of hidden counter with an explicit counter location, and then use a typed or untyped Dword Atomic operation message instead.</p>	KBL:ALL
0917	GTI	GAM		<p>Reset of an engine (non render) does not complete when there is a continuous stream of traffic comes from another engine. Another flavor of this issue is with VEBox, where VEBox reset does not complete when there's continuous polling happening</p>	KBL: UNTIL_F0



## Workarounds

BSpec ID	Functional Area/Component	Workaround Name	Workaround Description	Valid Steppings
			<p>from VECS. The second flavor is seen with MI_SEMAPHORE_WAIT.</p> <p>WA:</p> <ol style="list-style-type: none"><li>1. for the first case (reset of A blocked due to traffic from B), the only workaround is to stall/stop engine B that is continuously generating traffic.</li><li>2. for the second case, the polling period need to be increased to let HW identify the fabric idleness and complete the Go=0 Ack for reset. Increase the poll interval in VECS_SEMA_WAIT_POLL (0x1A24C). Setting this to ius resolves the issue.</li></ol>	



## Display Workarounds

This page lists all BSpec workarounds for Display. Note that the functional area for each item is listed below, so you can search on this value or other content on this page. Also note that a "BSpec ID" has been assigned to make it easier to reference these items.

BSpec ID	Functional Area/Component		Workaround Name	Workaround Description	Valid Steppings
0342	Display	DisplayPort		<p><u>Not a workaround, this is required programming for all projects.</u></p> <p>DP MST requires certain VC payload size values.</p> <p>VC payload must be multiple of 4 in x1 lane config, 2 in x2, 1 in x4. See transcoder M/N Values.</p>	All
0346	Display	DisplayPort		<p>Aux channel transactions get intermittent NAK errors with some receivers.</p> <p>WA: Do not use the 400us Aux timeout. Increase DDI_AUX_CTL bits 27:26 Time out timer value to at least 600us 01b when doing DDI aux transactions.</p> <p>Merged with #0347</p> <p><u>This becomes standard required programming for all subsequent projects.</u></p>	All
0371	Display	Panel fitter	WaPanelFitterDownscale	<p><u>Not a workaround, this is required programming for all projects.</u></p> <p>When using panel fitter downscaling (pipe source size is larger than panel fitter window size) the maximum supported pixel rate will be reduced by the downscale amount, and watermarks must be adjusted. Use panel fitter scale amount when calculating maximum pixel rate and watermarks.</p>	All



## Workarounds

BSpec ID	Functional Area/Component		Workaround Name	Workaround Description	Valid Steppings
0373	Display	Panel power sequencing	WaVDDOverrideT4Power	<p><u>Not a workaround, this is required programming for all projects.</u></p> <p>When software clears the panel power sequencing VDD override bit from 1 to 0 (disable VDD override) it must ensure that T4 power cycle delay is met before setting the bit to 1 again.</p> <p>Use software timers to ensure T4 delay is met or use full panel power enable and not the VDD override.</p>	All
386	Display	PSR		PSR single frame update - When single frame update is enabled, the PSR CRC must be disabled for panel compatibility.	All
0387	Display	PSR		<p>PSR single frame update - Mask register write events when using single frame update.</p> <p><u>This becomes standard required programming for all subsequent projects.</u></p>	All
0388	Display	PSR		<p>PSR power saving - Mask PSR max timeout when PSR CRC is enabled.</p> <p><u>This becomes standard required programming for all subsequent projects.</u></p>	All
0471	Power	FBC		<p>First line of FBC getting corrupted when FBC compressed frame buffer offset is programmed to zero. Command streamers are doing flush writes to base of stolen.</p> <p>WA: New restriction to program FBC compressed frame buffer offset to at least 4KB. See</p>	All



Workarounds



BSpec ID	Functional Area/Component		Workaround Name	Workaround Description	Valid Steppings
				<p>FBC_CFB_BASE in North Display Registers. Additionally software must not use this first 4KB of graphics data stolen memory for anything else.</p> <p><u>This becomes standard required programming for all subsequent projects.</u></p>	
0477	Power	IPC		<p>IPC (Isoch Priority Control) may cause underflows.</p> <p>WA: Do not enable IPC in register ARB_CTL2</p>	All
0482	Power	PSR		<p>The following sequence is needed when disabling PSR Single Frame Update to workaround cases where the remote frame buffer update indicator becomes stuck if there is a single frame update exit event (pipe register write) around the time that single frame update is being disabled.</p> <ol style="list-style-type: none"> <li>1. Set 0x420B0 bit 11 to mask off flips.</li> <li>2. Set PIPE_MISC bit 21 to mask off pipe register writes.</li> <li>3. Clear SRD_CTL bit 31 to 0 to disable PSR.</li> <li>4. Wait for 2 vertical blanks for PSR to completely disable.</li> <li>5. Clear SRD_CTL bit 30 to 0 disable Single Frame Update.</li> <li>6. Restore PIPE_MISC bit 21.</li> </ol>	All



## Workarounds

BSpec ID	Functional Area/Component		Workaround Name	Workaround Description	Valid Steppings
				<p>7. Restore 0x420B0 bit 11.</p> <p>PSR can now be re-enabled if needed.</p>	
0484	Power	Watermarks		<p>Watermark memory latency data retrieved from GT driver mailbox data may not account for memory read latency.</p> <p>Depending on mailbox response, add 2 microseconds to the result for each level to compensate.</p> <p><u>This becomes standard required programming for all subsequent projects.</u></p>	All
0485	Power	Watermarks		<p>Notable Bspec correction. Not a workaround.</p> <p>Watermark memory latency data retrieved from GT driver mailbox data had incorrect dword ordering in earlier versions of the BSpec. BSpec is now corrected to show the first set of data has latency levels 0-3 and second set has levels 4-7.</p> <p>This becomes standard required programming for all subsequent projects.</p>	All
0529	Display	FBC		<p>Corruption in some cases when FBC is enabled and the plane surface format is in linear, tile Y legacy, or tile Yf</p> <p>WA: Display register 4208Ch bit 13 must be set to 1b and bits 12:0 must be programmed with the compressed buffer stride value. The compressed buffer stride must be calculated using the following</p>	All

Workarounds



BSpec ID	Functional Area/Component		Workaround Name	Workaround Description	Valid Steppings
				<p>equation:</p> $\text{Compressed buffer stride} = \text{ceiling} \left[ \left( \frac{\text{at least plane width in pixels}}{32 * \text{compression limit factor}} \right) * 8 \right]$ <p>At least plane width = a value greater than or equal to the width of the plane. Software may choose to use a greater value in order to handle cases where the plane width is changing from frame to frame, especially because 4208C is not double-buffered and can't be changed on the fly while FBC is enabled. Compression limit factor is either 1, 2 or 4 based on the FBC_CTL Compression Limit field.</p>	
0531	Display	Render Compression		<p>Render decompression is broken when plane widths greater than 3840 are used with horizontal panning.</p> <p>WA: When the render compression is enabled with plane width greater than 3840 and horizontal panning (Start X Position in the PLANE_OFFSET register is not 0), the stride programmed in the PLANE_STRIDE register must be multiple of 4.</p>	All
0562	Power	FBC		<p>FBC sometimes causes screen corruption with package C states.</p> <p>WA: 'FBC Watermark Disable' bit in ARB_CTL register must be set to 1b.</p>	All
0827	Display	Planes		<p>Switching the plane format from NV12 to RGB and leaving system idle results in display underrun and corruption.</p>	All



## Workarounds

BSpec ID	Functional Area/Component		Workaround Name	Workaround Description	Valid Steppings
				WA: Set the bit 15 & bit 19 to 1b in the CLKGATE_DIS_PSL register for the pipe in which NV12 plane is enabled.	
0828	Display	PSR2		<p>PSR2 screen corruptions when multiple regions are updated in a single frame.</p> <p>WA: Set 0x42080 bit 3 = 1 before enabling PSR2. The register can safely remain set when PSR2 is disabled.</p>	All
0840	Display	Watermarks SAGV		<p>Programming needed for SAGV to prevent underflows in multi-display scenarios. See Display Watermark Programming - Watermark Calculations section.</p> <p>This becomes standard required programming for subsequent core projects.</p>	All
0851	Display	FBC	WaFbcNukeOn3DBIt	To prevent missed invalidations around the time FBC is being enabled, FBC render tracking must use the "Render Tracking With Nuke" method. See Frame Buffer Compression page.	All
0856	Display	Memory Bandwidth		<p>Display underflow with high resolutions and multiple displays.</p> <p>WA: Restrict display configurations to fit within system memory bandwidth threshold specified in the Display Mode Set -&gt; Display Resolution Support page.</p> <p>Increase watermarks at some system memory bandwidth thresholds. See Display Watermark Calculations.</p>	All

Workarounds



BSpec ID	Functional Area/Component		Workaround Name	Workaround Description	Valid Steppings
				<p>The restriction to fit within memory bandwidth threshold is required programming for all subsequent projects. The threshold can change from project to project and will be listed on the <a href="#">Display Resolution Support page</a>.</p>	
0857	Display	Planes		<p>Display underrun issues with Y &amp; Yf Tiling. WA: Set the bit 13 of MMIO register 0x46430 to 1b.</p>	All
0859	Display	FBC	WaFbcWakeMemOn	<p>This workaround helps to achieve better idle power savings when FBC is enabled.  WA: Set ARB_CTL FBC Memory Wake to 1'b1.</p>	All
0868	Display	GMBUS		<p>4 block EDID failures.  WA:  Set 0x4653C[14] = 0x1 to disable clock gating when the north display GMBUS function is used.  Set 0xC2020[31]=0x1 to disable clock gating when the south display GMBUS function is used.</p>	All
0873	Display	FBC		<p>Screen corruption observed with FBC when the front buffer is updated by host modify.  WA: To prevent missed host invalidations around the time FBC is being enabled, enable Nuke on modify. Set bit 23 of MMIO register 0x43224 to 1'b1.</p>	All



## Workarounds

BSpec ID	Functional Area/Component		Workaround Name	Workaround Description	Valid Steppings
0880	Display	Clocks		<p>Timeout for display cdclk mailbox programming increased from 1ms to 3ms to account for some corner cases that can exceed 1ms.</p> <p><u>This becomes standard required programming for all subsequent projects.</u></p>	ALL
0881	Display	Clocks		<p>Display PLL workaround for signal integrity when using the 2.16 or 4.32 GHz eDP link rate together with spread spectrum clocking. The GT driver pcode mailbox has to be programmed to override some DPLL internal values. See Display -&gt; North Display Engine Registers -&gt; Clocks -&gt; Port Clock Programming.</p>	All
0883	Display	FBC	WaFbcHighMemBwCorruptionAvoidance	<p>When FBC is enabled sometimes screen corruptions/system hangs observed under high memory bandwidth conditions.</p> <p>WA: Set the bit 8 of MMIO register 0x43224 to 1b.</p> <p>Set ARB_CTL FBC Memory Wake to 1b (from #0859). This memory wake setting is also preferred for better power savings with FBC.</p>	KBL:*:A KBL:*:B
0893	Display	Memory Bandwidth		<p>Display underflow with high resolutions and multiple displays when using dual channel single rank memory.</p> <p>WA: Increase watermarks at some system memory bandwidth thresholds. See Display Watermark Calculations.</p>	All

Workarounds



BSpec ID	Functional Area/Component		Workaround Name	Workaround Description	Valid Steppings
1106	Display	NV12, Rotation, Horizontal flip		<p>Display corruption/color shift observed when using NV12 with 270 rotation or 90 rotation + horizontal flip.</p> <p>WA: NV12 with 270 rotation or 90 rotation + horizontal flip requires the programmed plane height to be a multiple of 4.</p>	All
1107	Display	Transition Watermark		Transition watermarks must not be enabled.	All
1110	Display	FBC + PSR/PSR2		<p>Missing flips when FBC is enabled with PSR link off/PSR2 deep sleep scenarios.</p> <p>WA: When FBC is enabled with PSR/PSR2, set bit 30 of MMIO register 0x420CC to 1b.</p>	KBL:*:A KBL:*:B
1125	Display	Watermarks, render compression		<p>Render compression watermark adjustment.</p> <p>This was a late addition to the Bspec, but not previously tracked as a workaround. See the Watermark Calculations page for details.</p> <p>WA: If Render Decompression enabled and latency level 0: Result Blocks = Result Blocks + Y tile minimum. Then ensure that the result blocks for higher latency levels are all at least as high as the new level 0.</p>	All
1126	Display	Watermarks		<p>Watermark adjustment.</p> <p>This was a late addition to the Bspec, but not previously tracked as a workaround. See the Watermark Calculations page for details.</p>	All



## Workarounds

BSpec ID	Functional Area/Component		Workaround Name	Workaround Description	Valid Steppings
				<p>WA: If latency level 1 through 7 and Y tile: Result Blocks = Result Blocks + Y tile minimum; Result Lines = Result Lines + Minimum Scanlines for Y tile</p> <p>If latency level 1 through 7 and not Y tile: Result Blocks = Result Blocks + 1</p>	
1131	Display	VTd		<p>Display underflow and flicker when VTd is enabled with a frame buffer having a mix of VTd 4K, 2MB and 1GB pages.</p> <p>WA: When VTd is enabled, all the extra dummy PTE entries must be mapped to pages of same size (4K, 1GB or 2MB).</p> <p>All the extra entries shall map to the same dummy page. This dummy page padding is required immediately after the display active fetch area. If any of the display features (like panning, clipping, collage displays, planar YUV surfaces) can't meet the above requirement it must not be enabled.</p> <p>See PLANE_SURF restrictions for Extra Page Table Entries allocation requirements.</p>	All
1132	Display	64bpp		<p>Bandwidth limitations in the display data buffer output can cause underflow with 64bpp pixel formats when multiple planes are enabled at high resolutions.</p> <p>The 64 bits per pixel source pixel format can only be used on a single plane and when only a single pipe is enabled.</p>	All



Workarounds



BSpec ID	Functional Area/Component		Workaround Name	Workaround Description	Valid Steppings
1134	Display	GMBUS		<p>GMBUS bit bashing failures because GPIO pin is unexpectedly in busy state.</p> <p>WA: When starting bit bashing, first write GPIO_CTL = 0x00000404.</p>	All
1136	Display	PSR		<p>Display underrun with PSR single frame update and planes with less than watermark level 7.</p> <p>WA: When using PSR single frame update, all enabled planes must have enabled up to watermark level 7. If any plane cannot support level 7, then single frame update cannot be enabled.</p>	KBL*:A KBL*:B
1141	Power	IPC		<p>IPC (Isoch Priority Control) may cause underflows.</p> <p>WA: When IPC is enabled, watermark latency values must be increased by 4us across all levels. This brings level 0 up to 6us..</p>	All
1142	Display			<p>Underruns found with FBC, but also could impact cases without FBC.</p> <p>WA: Before enabling display planes or cursor, program 0x42084 bits 14:13=10b and 0x42080 bit 22=1b. Keep this value while planes or cursor are enabled. The value is ignored while planes and cursor are all disabled. The same programming is used with and without FBC.</p>	KBL:SIWA_FROM_CO
1143	HDMI			<p>For HDMI the voltage swing programming for a port is locked at the value used when the port is first enabled after boot or package C10. Override programming is needed to allow the swing to change after that point, such as for DP++ ports or</p>	All



## Workarounds

BSpec ID	Functional Area/Component	Workaround Name	Workaround Description	Valid Steppings
			<p>electrical validation.</p> <ol style="list-style-type: none"> <li>1. Just before enabling DDI_BUF_CTL for HDMI in the port enable sequence.</li> <li>2. Set override for this DDI.               <ul style="list-style-type: none"> <li>○ DDIB: 0x420C0 19:18 = 11b</li> <li>○ DDIC: 0x420C4 19:18 = 11b</li> <li>○ DDID: 0x420C8 19:18 = 11b</li> <li>○ DDIA: 0x420CC 19:18 = 11b</li> </ul> </li> <li>3. Wait 1us for DDI to pick up the swing value.</li> <li>4. Clear override for this DDI to 00b.</li> <li>5. Continue with enabling DDI_BUF_CTL.</li> </ol>	
1144	Audio		<p>DisplayPort audio corruption or video underflow with some clock frequencies and audio configurations.</p> <p>WA:</p> <p>If (DP port width x4 AND link rate HBR2 AND CDCLK frequency &lt; 432 MHz) {</p> <p style="padding-left: 40px;">If (audio clock frequency &gt; 96 KHz OR 8 audio channels used OR audio configuration unknown) {</p> <p style="padding-left: 80px;">DisplayPort audio cannot be enabled at this CDCLK frequency.</p>	All

Workarounds



BSpec ID	Functional Area/Component		Workaround Name	Workaround Description	Valid Steppings
				<pre> }  Else {  Set register (0x420C0 for audio on transcoder A, 0x420C4 for transcoder B, 0x420C8 for transcoder C) bit 13 to 1 before enabling DisplayPort audio.  }  }                     </pre>	